

# RESISTANCE METER

PRS-812

User Manual





# Table of Contents

---

## PROSTAT® PRS-812 RESITANCE METER

Section	Topic	Page
I.	Introduction & Description	4
II.	Cautions & Warnings	7
III.	Controls, Connections & Indicators	9
IV.	Battery Installation and Replacement	15
V.	Setup & Calibration	16
VI.	Instrument Operation	18
VII.	Instrument Maintenance	31
VIII.	Warranty Information	32
	General Specifications	34
	Instrument Controls	35

## I. Introduction & Description



**Figure 1: PRS-812 during power up**

The PRS-812 Resistance Meter makes precision resistance measurements from 0.1 up to  $1.0 \times 10^{12}$  ohms with an overall measurement tolerance of  $\pm 5\%$ . It is capable of measuring up to  $2.0 \times 10^{14}$  ohms with tolerance depending on procedures and conditions. The PRS-812's wide range and close tolerance make it the ideal ESD Auditing instrument for measuring resistance to a variety of ESD and general industry specifications. It is operated by programmed microprocessors that control the instrument's measurement process, resistance auto ranging, test voltage selection, electrification periods, and display functions. It can be operated in either fully automatic or manual modes, or a combination of automatic and manual modes.

The PRS-812 is unique in that it records and stores up to 80 resistance measurements in its own non-volatile memory register. Stored data is summarized with a push of a button.

Its accuracy is based on its ability to rapidly make several measurements each second, and average them until a stable set of eight measurements, all within 5% tolerance, are obtained. The final averaged data is displayed as the resistance measurement. Typically, measurements at less than 1 ohm are within 5% of tolerance, and those between 1.0 and  $1.0 \times 10^{12}$  ohms are within 0.5% of laboratory references

While quite sophisticated in design, the PRS-812 Resistance Meter is easy to use and extremely helpful in making accurate ESD auditing measurements, or general resistance and continuity checks.

### CAUTION

To avoid electrical shock or damage to the PRS-812 Resistance Meter, read this manual completely before installing batteries or using the instrument.

#### A. Measurement Applications

The PRS-812 Resistance Meter is designed to measure resistance characteristics of electrostatic discharge (ESD) control materials and products to current ESD industry standards, including:

Wrist Straps (ANSI/ESD S1.1)  
Flooring (ANSI/ESD STM7.1)  
ESD CP Grounds (ANSI/ESD S6.1)  
Footwear (ANSI/ESD STM9.1)  
Equipment (ESD SP10.1)  
Material Handling Containers

Garments (ESD STM2.1)  
Worksurfaces (ANSI/ESD S4.1)  
Carts & Seating (ANSI/ESD STM 12.1)  
Workstations  
Production Aids & Hand Tools  
Packaging (ANSI/ESD STM11.11, ANSI/ESD STM11.12 & ASTM 257), and Other ANSI/S20.20 ESD Program Control Elements

**Note:** Additional fixtures and electrodes supplied separately are required for many of these measurement.

**B. PRS-812 Resistance Meter Components:**

The PRS-812 Resistance Meter includes the following items:

1. PRS-812 Resistance Meter Instrument with 2 each 9V alkaline batteries.

<p><b>IMPORTANT NOTE</b></p>
------------------------------

<p>Only use alkaline batteries for optimal performance.</p>
---

2. Two 10-foot leads (PRS-800LB & PRS-800LR) for general audit measurements up to  $1.0 \times 10^{12}$  ohms.
3. One heavy duty, black “Bulldog” clip (PRS-801BC)
4. Two Metal Alligator Clips (PSI-870MAC)
5. One Audit Test Bed (PTB-915)
6. One calibration shunt for low range adjustment (PRS-801CC)

Optional accessories are available for the PRS-812 Resistance Meter. Visit [www.prostatcorp.com](http://www.prostatcorp.com) for additional information.

**C. PRS-812 Basic Description & Functions**

The PRS-812 Resistance Meter has several test, display and data logging functions:

1. The PRS-812 six basic measurement modes are described in the following table

MODE	DISPLAYED UNITS	INDICATION	RESIST. RANGE	TEST VOLTS	TEST FUNCTIONS
AUTOMATIC 1 [Default]	1.0EXX IND $\Omega$ - T $\Omega$	AUTO	AUTO.	AUTO.	AUTOMATIC RESISTANCE RANGE, TEST VOLTS, ELECTRIFICATION, DISPLAY HOLD  <b>SEE TABLE NOTE #1</b>
AUTOMATIC 2	OHMS $\Omega$ - T $\Omega$	AUTO	AUTO.	AUTO.	
MANUAL 1	1.0EXX IND $\Omega$ - T $\Omega$	MANUAL	MAN	MAN. or AUTO	TEST ONLY; NO DISPLAY HOLD UL= UNDER DECADE LEVEL OL= OVER DECADE LEVEL  <b>SEE TABLE NOTE #2</b>
MANUAL 2	OHMS $\Omega$ - T $\Omega$	MANUAL	MAN	MAN. or AUTO	
MANUAL/ AUTOMATIC 1	1.0EXX IND $\Omega$ - T $\Omega$	AUTO & MANUAL	MAN. Start AUTO Run	AUTO.	MANUAL SETUP STARTING DECADE, AUTO ADJUST RANGE, TEST VOLTS, ELECTRIFICATION DISPLAY HOLD  <b>SEE TABLE NOTE #3</b>
MANUAL/ AUTOMATIC 2	OHMS $\Omega$ - T $\Omega$	AUTO & MANUAL	MAN. Start AUTO Run	AUTO.	

**TABLE NOTES:**

- #1 AUTOMATIC: RESISTANCE RANGES IN AUTO 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+04 $\Omega$  (0.1 $\Omega$  - < 10K $\Omega$ )  
 @ 10V: 1.0E+04 TO <1.0E+06 $\Omega$  (10K $\Omega$  - < 1M $\Omega$ )  
 @100V: 1.0E+06 TO <2.0E+12 $\Omega$  (1M $\Omega$  - <200T $\Omega$ ) **See Note Below**
- #2 MANUAL: RESISTANCE RANGES IN MAN 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+05 $\Omega$  (0.1 $\Omega$  - <100K $\Omega$ )  
 @ 10V: 1.0E+03 TO <1.0E+09 $\Omega$  (1K $\Omega$  - <1G $\Omega$ )  
 @100V: 2.0E+05 TO <2.0E+12 $\Omega$  (200K $\Omega$  - < 200T $\Omega$ ) **See Note Below**
- #3 AUTO-MANUAL: (Same as AUTOMATIC)  
 RESISTANCE RANGES IN AUTO-MANUAL 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+04 $\Omega$  (0.1 $\Omega$  - < 10K $\Omega$ )  
 @ 10V: 1.0E+04 TO <1.0E+06 $\Omega$  (10K $\Omega$  - < 1M $\Omega$ )  
 @100V: 1.0E+06 TO <2.0E+12 $\Omega$  (1M $\Omega$  - <200T $\Omega$ ) **See Note Below**

2. The PRS-812 provides three separate test voltages for resistance measurements as indicated in the table, above:

<10 Volts  
 10 Volts  
 100 Volts

In **AUTOMATIC** and **AUTOMATIC/MANUAL** modes the instrument automatically controls voltage and resistance range based on resistance characteristics of materials being measured. In the **MANUAL** mode the operator may select test voltage and and resistance range. Note that the most efficient mode of operation in **AUTOMATIC/MANUAL** for maximum battery life.

3. The PRS-812 displays resistance Measurements in several ways:
- 14 factory programmable LED's each representing one order of magnitude from  $<10^3$  to  $>10^{12}$  ohms. LED's have three colors, including:

GREEN  
RED  
YELLOW/ORANGE

**NOTE**

The PRS-812 provides very accurate measurements up to  $1.0 \times 10^{12}$  ohms, and has the capability to display values up to  $2.0 \times 10^{14}$  ohms. However, the user should be aware that accuracy degrades rapidly above  $1.0 \times 10^{12}$  ohms.

- The large Liquid Crystal Display (LCD) includes an analog (1 - 10) scale and X1, X10 and X100 multiplier indication for measurement in  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$  and T $\Omega$ .
  - Digital measurements are provided using integers and  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$ , T $\Omega$  indicators, or in exponential format (1.0EXX) with  $\Omega$  -T $\Omega$  indicators.
4. The PRS-812 includes data logging (storage) capabilities for up to 80 data points when **RECORD** is selected. The instrument will provide access to the memory register, calculate and display Minimum, Maximum and Average of all measurements in the instrument's memory whenever **RECALL** is selected.

## II. Cautions & Warnings

As with any electrical device, use proper safety precautions and safe measurement procedures to avoid personnel shock and arc discharge.

- The PRS-812 Resistance Meter is battery operated and delivers test voltages up to 100 volts.  
**IMPORTANT:** Only use alkaline batteries in the PRS-812.
- The instrument is current limited for safety, however, if improperly used it may be capable of delivering an annoying shock to a person touching conductors energized by the PRS-812, particularly at 100 volts.
- While current limited, a hazard exists in personnel reaction to a potential shock.
- To avoid personnel shock, follow the General Operations instructions at all times. Do not touch energized electrodes or fixtures when power is applied except as specifically described in this and accessory instructions.
- Do not operate or store the instrument in damp environments or wet conditions.

**CAUTION**

Storage or use of this instrument in high humidity, damp or wet conditions may cause damage to the instrument's electronic circuits, effect performance and can increase the possibility of personnel shock or arc discharge.

- F. Do not use the PRS-812 in combustible or explosive environments

**WARNING**

Improper handling and use of energized circuits may cause arc discharge, which in turn may cause the ignition of combustible materials or fumes. Do not use exposed energized circuits in flammable areas.

- G. Do not attempt to measure energized circuits with the PRS-812
- H. Do not use the PRS-812 if it becomes damaged in any way
- I. Only Prostat trained instrument personnel should attempt to service or repair the PRS-812
- J. Other Safety & Operating Considerations
1. This manual displays cautions and warnings alerting the user to hazardous operation and servicing conditions. **CAUTION** or **WARNING** headings throughout this publication flag this information, where appropriate. Follow all caution and warning instructions at all times.
  2. The PRS-812 is a precision instrument and should be operated by experienced personnel familiar with the use and handling of devices containing power supplies.

**CAUTION**

The PRS-812 Contains Electrostatic Discharge Sensitive (ESDS) components and includes precision alignment of circuit elements. Only Prostat trained and ESD Qualified instrument repair personnel should perform service.



3. The PRS-812 contains Electrostatic Discharge Sensitive (ESDS) components. Qualified personnel should service it only at ESD Controlled workstations. Do not attempt to dismantle the PRS-812



without Prostat's authorization and expert supervision. The instrument contains exceptionally clean circuits that are aligned and adjusted in a precise manner for optimal operation and accurate performance. Unauthorized opening of the PRS-812 housing will void the instrument's warranty.

**WARNING**

Unauthorized opening of the PRS-801 case or dismantling in any manner  
***WILL VOID THE INSTRUMENT'S WARRANTY.***

4. Read this manual in its entirety before installing batteries or using the PRS-812.
5. Do not drop or cause unnecessary mechanical shock to your PRS-812 instrument.
6. Store the instrument in a clean, dry environment. Do not expose the instrument to wet, extremely hot or cold conditions.
7. If the unit is stored in a cold environment, allow it to stabilize at room temperature before powering up the unit. This will prevent damage due to condensation that may accumulate on the instrument's circuit boards.

### III. Controls, Connections & Indicators

Before operating the PRS-812 instrument become familiar with each control and display function. A thorough understanding of the instrument's operation will make its use a pleasant experience, enhance measurement accuracy, avoid mistakes and prolong the life of the instrument.

#### PRS-812 CONTROLS:

##### [1] FUNCTION/ MODE      Toggles Through Six Operation Modes

(1) AUTO: (AUTOMATIC) displays data in exponential format 1.0EXX

**NOTE:** AUTO in exponential format, e.g., 1.3E05, is the Default start up mode when the instrument is turned ON.

(2) AUTO: (AUTOMATIC) displays data in  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$  and T $\Omega$ . The instrument controls resistance ranges, test voltage and electrification periods in AUTOMATIC mode.



Figure 2: PRS-812 Controls & Display Indicators

(3) MANUAL: displays data in exponential format 1.0EXX

(4) MANUAL: displays data in  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$  and T $\Omega$

In **MANUAL**, the operator selects resistance range in single decade increments. Test voltage may be selected by the operator, or allowed to function automatically based on resistance range selected. The operator determines electrification period in seconds (SEC) using the displayed timer in the center of the LCD.

(5) AUTO-MANUAL: displays data in exponential format 1.0EXX

(6) AUTO-MANUAL: displays data in  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$  and T $\Omega$

In **AUTO-MANUAL** the operator may select the initial resistance range in decade increments. Once set, the PRS-812 starts the measurement process from the preset resistance decade, rather than re-zeroing itself for each measurement. This feature saves measurement cycle time and extends battery life. In this mode the instrument automatically controls test voltage, range and measurement electrification period.

**[2] RESISTANCE RANGE SELECTION**

Two Triangular Arrows Buttons, UP (↑) and DOWN (↓), select Resistance Measurement Range in single orders of magnitude while in **MANUAL** or **AUTOMATIC/MANUAL** modes

**[3] TEST VOLTS**

Manual Selection of <10, 10 or 100 volts in **MANUAL** selects initial test voltage. **MANUAL** Test Voltage & Resistance Limits are as follows:

**@<10V:** 0.1 to <1.0E+05Ω (0.1Ω - <100KΩ)

**@ 10V:** 1.0E+03 to <1.0E+09Ω (1KΩ - <1GΩ)

**@100V:** 2.0E+05 to <2.0E+14Ω (200KΩ - <200TΩ)

**NOTE:** Optimal minimum measurement in **MANUAL** using 100 volts is 2.0E+05.

**[4] RECORD/RECALL**

If **REC** is not displayed in the lower left corner of the LCD, pressing **RECORD/RECALL** once turns Memory Register ON [**REC** will then be displayed in LCD]. If **REC** is ON and measurement data is stored in memory, pressing **RECORD/RECALL** once will provide access to the memory register. Pressing **RECORD/RECALL** successively will calculate and sequentially display Minimum [**MIN**], Maximum [**MAX**] and Average [**AVG**] of data stored in the Memory Register. If memory is **ON** and register contains stored data pressing **RECALL** will provide the following information:

**First Press RECALL:** Provides access to data in Memory

**NOTE:** **MEM XX** Flashes in LCD indicating number of data points in the register and the last measurement is displayed. Pressing DOWN (↓) and UP (↑) displays other data points and their respective position in the register is shown in the **MEM XX** section of the LCD.

**Second Press RECALL:** Displays MIN Data Point in Memory

**Third Press RECALL:** Displays MAX Data Point in Memory

**NOTE:** When displayed, **OL** [Over Level] indicates a measurement greater than (>) 2.0x10<sup>14</sup> ohms, which is beyond the measurement capability of the PRS-812.

**Fourth Press RECALL:** Displays **AVG** of all Memory Data Points

**NOTE:** **OL** [Over Level] measurements [>2.0x10<sup>14</sup> ohms] are not included in displayed average (**AVG**) calculation.

**Fifth Press RECALL:** Returns System to normal operations

**NOTE:** If in **RECALL** mode, pressing **RESET** will return the instrument to normal measurement operations.

**NOTE**

If **RECALL** is not pressed, a fifth time **OOPS** will be displayed in the LCD when **TEST** is next pressed. To Clear **OOPS**, press **RESET**. The instrument will return to normal operations.

**[5] CLEAR**

In normal operations **CLEAR** erases data in Memory Register, discards most recent measurement, or turns the **REC** function **OFF** as follows:

- a. When in any operation mode, and **HOLD** is not displayed, pressing **CLEAR** will erase all data stored in Memory.

**NOTE**

The process of turning the **REC** function **OFF** will clear the Memory Register of all stored data. Be sure that this is indeed desirable before pressing the **CLEAR** button.

- b. If a measurement is displayed in **HOLD**, prior to pressing **RESET** button pushing **CLEAR** will discard that held value and will not enter it into Memory. Other data in Memory Register remains intact.
- c. If reviewing data in the Memory Register while in the **RECALL** mode, pressing **CLEAR** will discard the displayed data point. Other data in Memory Register remains intact and indexes down one space to replace the discarded data point.
- d. When in any operation mode, and **HOLD** is not displayed, pressing **CLEAR** will erase all data stored in the Memory Register. Pressing **OFF** will disable the **REC** mode and the instrument will be de-energized. When powered up again the **REC** mode will remain disabled until **RECORD/RECALL** is pressed once.

**[6] ON/OFF**

Turns instrument **ON** for normal operations, performs functional & Battery tests, turns instrument **OFF**.

**[7] BATT. TEST**

Displays **GOOD** on LCD if battery provides acceptable voltage for accurate measurements, or displays **Lo** if unacceptable and batteries require replacement.

**[8] RESET**

Saves measurement and prepares instrument for next test cycle, i.e., enters measurement into Memory Register if **REC** is **ON**, and clears **HOLD** and the LCD display between measurements.

**[9] TEST**

Begins measurement sequence in accordance with selected mode

**[10] BATTERY  
BUSS CUT OFF**

Battery buss cut-off switch is used to isolate the main batteries from the instrument's circuit during battery change, instrument storage and transport.

**CAUTION**

Switch battery buss to the OFF position before changing batteries to avoid reverse polarity damage to the instrument.

**LCD DISPLAY ELEMENTS**

**[11] Colored LED's** 14 LED's across the top of the PRS-812 indicate measurement order of magnitude in decades from  $<10^3$  to  $>10^{12}$  ohms.

**NOTE**


The PRS-812 provides very accurate measurements up to  $1.0 \times 10^{12}$  ohms, and has the capability to "indicate" values up to  $2.0 \times 10^{14}$  ohms. However, the user should be aware that accuracy degrades rapidly above  $1.0 \times 10^{12}$  ohms.

**[12] PRS-812 Liquid Crystal Display (LCD) Elements:**

**AUTO** When ON Indicates instrument in **AUTOMATIC** mode

**MANUAL** When ON indicates instrument in **MANUAL** mode

When **AUTO** and **MANUAL** are **ON**, indicates instrument is in **AUTO-MANUAL** mode.

**Analog Scale  
& X100 Indicator**

The one decade analog scale elements darken to indicate measurement in teger. X1, X10 or X100 darken to indicate the scale multiplier. Combine the Analog indicators with Ω, KΩ, MΩ, GΩ and TΩ symbols to obtain an analog measurement.


**MEM 00**

Provides the number of data points stored in the Memory Register when **REC** is **ON** and instrument is **RESET** in preparation for a new measurement. The Memory Register can store up to 80 data points.

Also identifies a displayed data point's position in the Memory Register when in the **RECALL** mode.

**00 SEC**

Display's electrification period required for the measurement when in **TEST** during **AUTOMATIC** and **AUTO-MANUAL** measurement modes. In **MANUAL**, provides continuous measurement timing up to 99 seconds, then restarts at 0 seconds.

<b>MIN</b>	Displayed when <b>RECALL</b> button is pushed second time while in <b>REC</b> mode. Number displayed when <b>MIN</b> is indicated is the Minimum data value in Memory Register.
<b>MAX</b>	Displayed when <b>RECALL</b> button is pushed a third time (sequentially) in <b>REC</b> mode. Number displayed when <b>MAX</b> is indicated is the Maximum data value in Memory Register.
<b>AVG</b>	Displayed when <b>RECALL</b> button is pushed the fourth time (sequentially) in <b>REC</b> mode. Number displayed when <b>AVG</b> is indicated is the Average of all data values in Memory Register that are less than $2.0 \times 10^{14}$ ohms. (OL's are not included in averaging calculation.)  <b>Note:</b> Either the <b>RECALL</b> button must be depressed a fifth time or <b>RESET</b> pressed to return the system to its operational, measurement mode.
<b>REC</b>	Indicates that the Memory Register is <b>ON</b> and is Recording data each time the <b>RESET</b> button is depressed after a <b>TEST</b> measurement.
<b>Ω</b>	Ohms: Indicates measurement between 0.1 and 999 ohms
<b>KΩ</b>	Indicates measurements from 1,000 ( $1.0 \times 10^3$ ) to 990,000 ( $9.9 \times 10^5$ ) ohms
<b>MΩ</b>	Indicates measurements from 1,000,000 ( $1.0 \times 10^6$ ) to 999,000,000 ( $9.9 \times 10^8$ ) ohms
<b>GΩ</b>	Indicates measurements from 1,000,000,000 ( $1.0 \times 10^9$ ) to 999,000,000,000 ( $9.9 \times 10^{10}$ ) ohms
<b>TΩ</b>	Indicates measurements from 1,000,000,000,000 ( $1.0 \times 10^{12}$ ) to 200,000,000,000,000 ( $2.0 \times 10^{14}$ ) ohms
<b>&lt;100 V</b>	Indicates <10, 10 or 100 volts being applied as the test voltage.
<b>HOLD</b>	Indicates measurement is complete at the end of a <b>TEST</b> cycle. Holds data point in display until instrument is <b>RESET</b> or <b>CLEAR</b> is depressed.
	Battery indication for low voltage

#### PRS-812 Connections

<b>[+] Positive Terminal</b>	Power terminal for supplying Test Voltage to fixture or material under test.
<b>[-] Negative Terminal</b>	Sensing Terminal for measurement of current (I) through fixture or material under test.



## Battery Compartment

Located in lower section of case, opposite LCD display. Holds two 9V-transistor batteries. Two screws secure the battery cover. Note: Use only Long Life Alkaline Batteries. Remove batteries when instrument is not in use for long periods of time.



Figure 3: Opening Battery Compartment



Figure 4: Install 2 each 9V Alkaline Batteries

## IV. Battery Installation (See Figures 3 & 4)

For optimal battery life and avoid instrument damage, always replace the batteries with high energy, alkaline batteries. Failure to do so will result in a diminished battery life, measurement error and potential instrument damage that could void the warranty.

The battery caps on the instruments you have purchased are designed to fit snugly. Please follow the directions below for safe replacement of batteries.

- A. Slide battery bus switch to the **OFF** position (see figure 3).
- B. Carefully remove the battery cover from the instrument.
- C. Gently take the batteries from the battery compartment.
- D. Unwind any battery lead that is wrapped around the top of the battery terminal. Do not pull battery connection leads - this could cause instrument damage.
- E. Very carefully place a flat head screwdriver between the battery terminals and gently lift the battery cover from the battery.

- F. Properly dispose of any old batteries.
- G. Position the new alkaline battery under the battery cover.
- H. With your thumb, press the terminals in place one at a time.
- I. Carefully wind any excess battery lead around the battery terminal below the cap. To avoid instrument damage, do not pull battery connection leads
- J. Place the batteries back into position with the battery terminal covers facing the lead spurce within the battery case shown in figure 4.
- K. Carefully position the instrument battery cover back into place without force.
- L. Replace the battery cover screws.
- M. Slide battery buss switch to the **ON** position.

Following the above directions for battery replacement will insure that you do not damage the battery covers or wires during this process.

**NOTE**

It is recommended to measure the voltage of each battery with a multimeter. If the voltage of one battery measures at or below 6.75 volts, replace that battery. If both batteries measure at or below 6.75 volts, replace both batteries.

## V. Setup & Calibration

- A. Setting up the PRS-812 for low resistance range calibration
  - 1. Position Battery Buss Cut Off switch to OFF position
  - 2. To install batteries, remove two Phillips locking screws and cover. Attach two Long-Life, Alkaline 9V batteries to the battery connection terminals.
  - 3. Position batteries in compartment with power leads neatly positioned above battery connections. Carefully re-install battery cover and locking screws.

**NOTE**

Do Not change batteries with the battery buss **ON**. Always switch Battery Buss Cut Off to **OFF** when changing batteries. Should the **ON/OFF** button be depressed during battery change and Battery Bus is **ON** the instrument may lock up and not function properly or be seriously damaged. In this case, simply disconnect the batteries, then re-install with Battery Buss switch in the **OFF** position.

- B. Low Resistance Range (<10 Ohms) Calibration
  - 1. Install the calibration shunt (PRS-801CC) across the Negative (-) and Positive (+) Lead Terminals (Figure 5, below).





**Figure 5: Low Resistance Range Calibration Shunt Installation**

2. Press the Red **ON/OFF** power button. The instrument display should become energized, each LED will be tested in sequence, and **GOOD** will be displayed in the LCD if the batteries have sufficient test capacity (figure 9).



**Figure 6: Low Resistance Range Calibration using Reference Module**



**Figure 7: Start the Calibration Sequence by Pressing RESET then CLEAR within 1/2 Second**

3. Allow the instrument circuits to warm-up for a few minutes; approximately 2 - 3 minutes are sufficient, prior to completing the calibration sequence.
4. Press **MODE** once to shift display to ohms mode ( $\Omega$ ).
5. Press the Yellow **RESET**, then the Gray **CLEAR** button within 1/2 second. The message **CAL** will be displayed in the LCD. (See Figure 8)
6. Press the Yellow **RESET** button to complete low range (0.1 to 10 ohm) calibration. The **CAL** message will automatically be cleared when **RESET** is pressed. (See Figure 8)
7. Press the Green **TEST** button. Indicated resistance should be 1.02 ( $\pm 0.02$ ) ohms as shown in Figure 8. Press **RESET** to clear the display. NOTE: If 1.02 ( $\pm 0.02$ ) ohms is not displayed, repeat the calibration process.

8. Remove the calibration shunt assembly from the lead terminals
9. The PRS-812 is now ready for wide range measurements from 0.1 to 1.0E+12 Ohms



**Figure 8: Complete Calibration Sequence by Pressing RESET. To confirm Calibration, Press TEST to measure the Calibration Shunt resistance. Shunt resistance should display 1.02 Ohms  $\pm 0.02$  Ohms**

## VI. Instrument Operation

### A. Overview of PRS-812 Operation & Measurement Test Cycle Sequence

The following 10 points provide a general overview for calibrating and using the PRS-812 for resistance measurements.

1. Slide Battery Buss Cut Off switch to **ON**
2. Press Red **ON/OFF** button once to power up PRS-812
  - a. Instrument performs circuit check, and tests LED's, LCD display, and battery voltage.
  - b. LCD displays **GOOD** if battery voltage suitable for instrument operation; displays **Lo** if batteries require replacement
  - c. Instrument ends startup sequence in default **AUTO**, Exponent Display Mode 1.0EXX
3. Select Function Mode if other than **AUTO**, Exponent Display Mode 1.0EXX is desired by pressing **MODE** button
4. Perform low resistance range calibration after 3 minute instrument warm-up, if desired
  - a. Install Calibration Shunt between positive (+) and negative (-) terminals
  - b. Press **RESET** then **CLEAR** within  $\frac{1}{2}$  second

- c. **CAL** is displayed in LCD
  - d. Press **RESET** to calibrate instrument to shunt reference
  - e. Press **TEST** to measure shunt resistance of  $1.02 \pm 0.02$  ohms ( $\Omega$ )
  - f. Press **RESET** button to prepare instrument for the next measurement
  - g. Repeat calibration procedure if necessary
  - h. Remove Calibration Shunt
5. Carefully connect test leads to positive (+) [Power] and negative (-) [Sensing] terminals. Insert right angle sleeved banana into instrument terminal, press gently while twisting into position.
- Standard 10-foot test leads are used for general audit measurements, and provides excellent accuracy up to  $1.0 \times 10^{12}$  ohms
6. Connect test leads to electrodes, fixture or circuit to be measured
7. Press Green **TEST** button to initiate Automatic measurement Test Cycle
- a. The resistance range is reset to minimum ( $0.1\Omega$ ). It is automatically adjusted in conjunction with the resistance characteristics of the materials under test, based on:
    - (1) Test voltage; and,
    - (2) Current flow.
  - b. Test Voltage is reset to  $<10V$  and automatically increased in accordance with the following material resistance characteristics:
    - (1)  $<10$  Volts:  $0.1$  to less than  $1.0 \times 10^4$  ohms ( $0.1\Omega - <10K\Omega$ )
    - (2)  $10$  Volts:  $1.0 \times 10^4$  to less than  $1.0 \times 10^6$  ohms ( $10K\Omega - <1M\Omega$ )
    - (3)  $100$  Volts:  $1.0 \times 10^6$  to  $2.0 \times 10^{14}$  ohms ( $1M\Omega - 200T\Omega$ )
    - (4) When **OL** is displayed, it mean that the resistance is greater than  $2.0 \times 10^{14}$  ohms
  - c. Electrification period, i.e., the time period during which test voltage is applied to the material under test, is automatically adjusted to the PRS-812's measurement characteristics and industry standards (ANSI/ESD STM11.11). Typical electrification periods are:
    - (1)  $2$  to  $3$  Seconds:  $0.1$  to less than  $1.0 \times 10^4$  ohms ( $0.1\Omega - <10K\Omega$ )
    - (2)  $2$  to  $4$  Seconds:  $1.0 \times 10^4$  to less than  $1.0 \times 10^6$  ohms ( $10K\Omega - <1M\Omega$ )
    - (3)  $7$  to  $8$  Seconds:  $1.0 \times 10^6$  to  $>1.0 \times 10^{12}$  ohms ( $1M\Omega - >1T\Omega$ )
    - (4)  $15+$  Seconds:  $1.0 \times 10^{12}$  to  $2.0 \times 10^{14}$  ohms ( $1T\Omega - 200T\Omega$ )

8. When the PRS-812 displays and holds the final resistance measurement, **HOLD** is indicated in the lower, right corner of the LCD.

The PRS-812 is processor controlled to obtain hundreds of measurements per second, and to make rapid adjustments in resistance range and test voltage as necessary. It will display the resistance measurement of the material under test based on the following criteria:

- a. A digital numeric display is the averaged result of eight (8) individual, consecutive measurements, each within  $\pm 5\%$  of each other.
- b. The display is continuously recalculated and updated during the measurement's electrification period.
- c. The final displayed measurement is the averaged result of the last eight (8) individual, consecutive measurements, each within  $\pm 5\%$ , at the end of the electrification period.
- d. If the material or test conditions vary such that eight consecutive measurements, each within  $\pm 5\%$  of each other cannot be obtained, the PRS-812 will extend the electrification period until the measurement criteria are met; or,
- e. The electrification period will automatically be terminated and the most recent averaged result of eight (8) individual, consecutive measurements will be displayed and held. NOTE: Several material measurements that vary greater than 15 to 20 percent of each other typically indicate inconsistencies in the material or test conditions.
- f. In rare cases, when a stable measurement cannot be obtained the display will reset.

**NOTE:** When several "held" measurements vary greater than 15 to 20 percent of each other this typically indicates inconsistencies in the material or test conditions.

9. To save the displayed measurement in the Memory Register and prepare the PRS-812 for the next measurement, press the Yellow **RESET** button. Pressing **RESET** causes three functions:
  - a. Enters (saves) last measurement into Memory Register

**NOTE**

**REC** must be displayed in the lower, left corner of the LCD in order to enter the measurement in the Memory Register. If **REC** is not displayed, press **RECORD/RECALL** once, then press **RESET** to save the data.

- b. Increases LCD displayed number of data points in the Memory Register (**MEM**) by one, e.g., MEM 02
  - c. Returns the PRS-812 to its last function mode in preparation for the next measurement
10. To make several measurements, simply press **TEST** to obtain the next measurement, and then **RESET** to save it. Repeat the **TEST** and **RESET** process for each measurement.

**NOTE**

Be sure to press **RESET** after your last measurement to save it in your Memory Register before turning the PRS-812 OFF. If the instrument is turned **OFF** before pressing **RESET** the last measurement will be lost.

Good Measurement Practices, specific Operational Procedures and descriptions of functional modes are covered in detail, below.

**B. Good Measurement Practices**

Several factors will affect precision resistance measurements. Most practitioners are aware of the importance of using care when handling instruments, proper use of connections, lead resistance, grounding, and the impact of electrical or electrostatic fields on their equipment.

As with most very precise instruments, the PRS-812 circuits and its cables are sensitive to the effects of electromagnetic and electrostatic fields. These effects are minimized by instrument and test lead design. However, good measurement practices should be exercised at all times to ensure accuracy and repeatability. Follow the recommendations below to obtain optimal performance from the PRS-812.

**1. Instrument handling and preparation**

- a. Do not drop or cause mechanical shock to your instrument
- b. Store the instrument in a clean, dry environment. Do not expose the instrument to wet, extremely hot or cold conditions.
- c. If the unit is stored in a cold environment, allow it to stabilize at room temperature before powering up the unit.
- d. Be sure fresh batteries are installed when beginning an extensive measurement sequence. Periodically check the condition of your alkaline batteries by pressing **BATT. TEST**. If **Lo** is indicated, replace your batteries.

**OPERATIONAL NOTE**

Low voltage Batteries will affect measurement accuracy.

- e. When making resistance measurements below 10 ohms, perform The Low Range Calibration Procedure. Repeat the procedure to confirm the instrument's response.
- f. During resistance measurements, stand back, away from the instrument to avoid body capacitance or fields from effecting instrument accuracy.
- g. To avoid body fields from interfering with instrument accuracy, wear a wrist strap attached to a tested ESD ground to dissipate body charges.

## WARNING

To prevent electrical shock, Do Not Touch energized circuits, leads or fixtures while grounded.

Use pre-tested ground connections meeting local safety codes for personnel earth grounding. Refer to National Electrical Codes and ESD Association Standard S6.1 Grounding for information and procedures. Only qualified personnel should conduct ground test measurements.

2. Use only Prostat test leads, cables and accessories supplied with the PRS-812. Be sure that leads are properly connected to their respective terminals as described below.
  - a. The 10-foot general measurement leads are custom made of high quality, silicon rubber for maximum insulation properties and measurement accuracy. These leads are intended for general measurements up to  $10^{12}$  ohm range. Shielding is not incorporated in the 10-foot lead construction.
    - (1) When installed in the PRS-812 terminals, be sure the right angle sheathed banana connections are fully inserted and positively seated for full terminal contact.

## NOTE

Do not apply excessive force when mounting leads on the terminals to prevent deformation or damage to the terminal circuit board.

- (2) The straight, retractable-sheathed banana plugs are intended for connection to measurement electrodes, fixtures or clip accessories.
  - (3) The red lead should be installed in the positive (+) terminal and the black lead in the negative (-) terminals.
3. When making measurements in the manufacturing environment, move the instrument and test leads away from power cables and heavy electrical equipment to prevent electromagnetic interference.
4. If groundable fixtures are employed for material measurements, and when using 10-foot leads, attach an auxiliary lead from the fixture to an ESD safe earth ground.
5. Prior to making precision measurements, allow the PRS-812 to warm-up for 3 minutes, then perform the Low Resistance Calibration procedure. If several measurements are to be made, periodically check the instrument's calibration using the supplied calibration shunt.

### C. Operation in AUTOMATIC Modes

The PRS-812 was designed to simplify measurement standards and general rules for making wide range resistance measurements. The PRS-812's **AUTOMATIC** mode controls the critical aspects of Test Voltage, Resistance Range, and Electrification Period to meet ESDA Standard ANSI/ESD STM11.11 Surface Resistance, and other requirements. Most measurements can be performed in AUTOMATIC, which has two function modes:

AUTO Mode 1: Auto Exponential Display 1.0EXX plus  $\Omega$  indicators  
AUTO Mode 2: Auto Display in  $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$  and T $\Omega$  indicators

AUTO Mode 1 is the default functional mode when the PRS-812 is powered up. To change to AUTO Mode 2, simply press the MODE button once. The **AUTOMATIC** modes are used in measurements where the following attributes are desired:

- Automatic Test Voltage selection and control from 0.01 to 100 volts
- Automatic resistance scale control from 0.1 ohm to  $1.0 \times 10^{12}$  ohms (200 T $\Omega$ )
- Automatic Electrification Period timing based on the instrument's measurement capabilities and industry standards for measurement of ESD controlled materials.

In AUTOMATIC Modes, the PRS-812 performs the following functions during the Measurement Test Cycle once the **TEST** button is pressed:

1. Resets the **RESISTANCE RANGE** to minimum, i.e., 0.1 $\Omega$
2. Sets **TEST VOLTAGE** to <10 volts (millivolts), and applies initial voltage to material under test
3. Resets the **ELECTRIFICATION PERIOD** timer to 0 seconds, then starts timer
4. During Measurement Test Cycle:
  - a. Automatically adjusts **RESISTANCE RANGE** in accordance with material resistive characteristics
  - b. Automatically adjusts **TEST VOLTAGE** in accordance with material resistive characteristics and industry standards
  - c. Automatically adjusts **ELECTRIFICATION PERIOD** in accordance with material resistive characteristics and industry standards
5. At completion of Test Cycle, displays and **HOLDS** final resistance measurement, test voltage, order of magnitude (LED), analog scale & multiplier, and electrification time at end of electrification period.

#### D. General Automatic Mode Procedures

1. Attach the desired test leads to the fixture, electrodes or points to be measured

#### NOTE

The standard Prostat 10 foot test leads are intended for measurements up to the  $10^{12}$  ohm range. This is the maximum range of the PRS-812 for precision resistance measurements

2. Slide the Battery Buss Cut Off to the **ON** position. This connects the 9V batteries to the instrument's circuitry.



**NOTE**

Slide the Battery Buss Cut Off to the **OFF** position when the instrument is not in use, particularly during storage and transport to prevent unintentional instrument power up, and during battery replacement.

3. Press the Red **ON/OFF** button to power up the instrument.
4. The instrument will conduct a self-test, check its LCD display and LED lights, and test the batteries. If Batteries are acceptable **GOOD** will be displayed in the LCD (Figure 9).



Figure 9: PRS-812 Power Up tests display circuits, LED indicators and batteries

5. **AUTO** is displayed in the LCD.
    - a. The default Mode for the PRS-812 is Automatic Resistance Measurement in exponential format (1.0EXX).
    - b. If measurements are to be displayed in Ohms press the Gray **MODE** button once.
  6. If **REC** is not displayed in the lower left corner of the Liquid Crystal Display (LCD), press Gray **RECORD/RECALL** button once to display **REC** in LCD. This activates the Memory Register, enabling data storage.
  7. Press the Green **TEST** button to begin the **AUTOMATIC** measurement sequence. The instrument will automatically set the resistance range to 0.1 Ohms (1.0E-01), and select <10 volts to be applied to the Positive (+) Lead Terminal. The electrification timer will start counting seconds.
- E. Measurements Less than 10,000 ohms (<1.0x10<sup>4</sup> ohms):
1. When the resistance measurement is less than 1.0x10<sup>4</sup> ohms, test voltage will remain at <10V, the resistance range will be adjusted automatically and a stable resistance measurement will be obtained within 2.0 to 3.0 seconds.
  2. Once a stable measurement is confirmed and displayed by the instrument, **HOLD** will be energized in the LCD and the electrification timer will stop.



- An LED corresponding to the measurement's order of magnitude will be energized




Figure 10: Comparing PRS-812 Display in Automatic Ohms Mode and Automatic Exponential Mode after the same low resistance measurement.

F. Measurements from  $1.0 \times 10^4$  to less than  $1.0 \times 10^6$  ohms:

- When the resistance measurement is greater than  $1.0 \times 10^4$  ohms test voltage will automatically be increased to 10 volts, and the resistance range will be adjusted as necessary.
- A stable resistance measurement will be obtained within 2.0 to 4.0 seconds.
- Once a stable measurement is confirmed and displayed, **HOLD** will be energized in the LCD and the electrification timer will stop.




Figure 11: Test Voltage at 10 Volts from  $1.0 \times 10^4$  to  $<1.0 \times 10^6$  Ohms in Auto

4. An LED indicating the measurement's order of magnitude will be energized

G. Measurements from  $1.0 \times 10^6$  to less than  $1.0 \times 10^{12}$  ohms:

1. When the resistance measurement is greater than  $1.0 \times 10^6$  ohms the test voltage will automatically be increased to 100 volts, and electrification (Test Period) is automatically adjusted to >7.5 seconds.
2. Unless there are variations in the material or object being measured, a stable resistance measurement will be obtained in approximately 8.0 seconds.




Figure 12: Test Voltage at 100 Volts from  $1.0 \times 10^6$  to  $1.0 \times 10^{14}$  Ohms in Auto

**NOTE**

The PRS-812 can obtain an accurate resistance measurement within 2.5 seconds up to  $1.0 \times 10^{12}$  ohms, depending on material characteristics. An additional 5.0 seconds of electrification is applied in accordance with ESD Association S11.11 Surface Resistance Standard.

3. Once a stable measurement is confirmed and displayed by the instrument, **HOLD** will be energized in the LCD and the electrification timer will stop.
4. An LED corresponding to the measurement's order of magnitude will be energized

H. Measurements from  $1.0 \times 10^{12}$  to  $2.0 \times 10^{14}$  ohms:

1. When the resistance measurement is greater than  $1.0 \times 10^{12}$  ohms, the test voltage will remain at 100 volts and the instrument will continue to automatically adjust the resistance range.
2. The instrument's ELECTRIFICATION PERIOD is extended to a minimum of 15 seconds. Typically, a stable measurement will be obtained in 15.0 to 20.0 seconds.

3. Once a stable measurement is confirmed and displayed by the instrument, **HOLD** will be displayed in the LCD and the electrification timer will stop.

**NOTE**

The PRS-812 provides very accurate measurements up to  $1.0 \times 10^{12}$  ohms, and has the capability to display values up to  $2.0 \times 10^{14}$  ohms. However, the user should be aware that accuracy degrades rapidly above  $1.0 \times 10^{12}$  ohms. Errors above  $1.0 \times 10^{12}$  ohms depends on the user's procedures and environment.

4. An LED corresponding to the measurement's order of magnitude will be energized
- I. Measurements Greater Than  $2.0 \times 10^{14}$  ohms:
    1. If the measurement is greater than  $2.0 \times 10^{14}$  ohms, the test voltage will remain at 100 volts and the resistance range will be adjusted until the upper range is exceeded.
    2. **OL** (Over Level) will be displayed in the LCD, and the >14 LED will be energized.
    3. Once the instrument confirms a stable measurement, if any, **HOLD** will be displayed in the LCD and the electrification timer will stop. If a stable measurement cannot be obtained at this range **OL** will be displayed.
  - J. Resistance Measurements in **MANUAL MODE** of Operation

To select **MANUAL** in either Exponential (Mode 3) or Ohms (Mode 4) Display, use the **FUNCTION MODE** button to toggle through choices. Manual is used for a variety of applications where one desires to override Automatic functions:

- Measurement series where magnitude is in a defined decade and test voltage is fixed.
- When an extended electrification period may be desired
- Manual selection of test voltage for measurements not used with Automatic settings

The following summarizes **MANUAL MODE** Operations and assumes test leads are installed

1. Slide Battery Buss Cut Off switch to **ON** position
2. Press Red **ON/OFF** button once to power up the instrument.
3. Select **MANUAL MODE** by pressing the **MODE** button until **MANUAL** appears in the LCD.
  - a. Pressing **MODE** button two (2) times selects **MANUAL** Exponential display (1.0EXX)
  - b. Pressing the **MODE** button three (3) times selects **MANUAL** display in Ohms.
4. Set **RESISTANCE RANGE SELECTION** using the UP (↑) and DOWN (↓) arrow keys.
  - a. Range selection is made in one-decade increments and indicated with colored LED's.
  - b. For resistance ranges below <E3, use the LCD displayed decimal point (.) as a guide for setting the desired decade. The <3 LED will be illuminated.

5. Set test voltage by pressing **MANUAL SELECT TEST VOLTS** button until the desired voltage is displayed in lower right portion of LCD, i.e., <10, 10 or 100 Volts. **MANUAL** Test Voltage & Resistance Limits are defined below.

**IMPORTANT: Exceeding these limits may affect measurement accuracy.**

<b>&lt;10V:</b>	0.1 to <1.0x10 <sup>5</sup> ohms	(0.1Ω - < 100KΩ)
<b>10V:</b>	1.0x10 <sup>3</sup> to <1.0x10 <sup>9</sup> ohms	(1KΩ - < 1GΩ)
<b>100V:</b>	2.0x10 <sup>5</sup> to 2.0x10 <sup>14</sup> ohms	(200KΩ - 200TΩ)

**NOTE**

If a test voltage is not manually selected, test voltage control will default to Automatic Mode limits, switching higher or lower in accordance with resistance range selection.

6. Press **TEST** to begin the Measurement Test Cycle.
  - a. The instrument will:
    - (1) Apply and display the selected Test Voltage, or automatically default to and display the appropriate voltage for the selected resistance decade
    - (2) Self adjust the measurement resistance range to the selected decade
    - (3) Start the electrification period timer
  - b. If resistance is within the selected decade, the measurement and the electrification time will be displayed continuously in the LCD.
  - c. Pressing **RESET** will stop the Measurement Test Cycle, and simultaneously:
    - (1) Turn Test Voltage power supply OFF
    - (2) Save the displayed measurement in the Memory Register
    - (3) Add one data point to the MEM XX counter and display total number of data points in the Memory Register, e.g., MEM 05
    - (4) Prepare the instrument for the next measurement using the same Manual settings.
    - (5) Pressing **TEST** will start a new Measurement Test Cycle
7. If the resistance you are measuring is higher than the selected decade, **OL** (Over Level) will be displayed. To move the selected resistance range up to a higher decade:
  - a. Press **RESET** once to stop the Test Cycle. This does not add **OL** to Memory.
  - b. Press **MANUAL RESISTANCE RANGE SELECTION** up arrow (↑) to select the desired decade; the appropriate LED will illuminate indicating the current selection

- c. Press **TEST** to restart the Test Cycle
  - d. Repeat the **RESET**, Resistance Range adjustment and TEST sequence until a stable measurement is displayed
8. If the resistance is lower than the selected decade, **UL** (Under Level) will be displayed. To move the selected resistance range down to a lower decade:
- a. Press **RESET** once to stop the Test Cycle. This does not add **UL** to Memory.
  - b. Press MANUAL RESISTANCE RANGE SELECTION down arrow (↓) to select the desired decade; the appropriate LED will illuminate indicating the current selection
  - c. Press **TEST** to restart the Test Cycle
  - d. Repeat the **RESET**, Resistance Range adjustment and **TEST** sequence until a stable measurement is displayed

K. Resistance Measurements in the **AUTOMATIC/MANUAL** MODE of OPERATION

To select **AUTOMATIC/MANUAL** in either Exponential (Mode 5) or Ohms (Mode 6) Display, use the **FUNCTION MODE** button to toggle through choices. **AUTOMATIC/MANUAL** is used for a variety of applications where one desires to reduce Measurement Test Cycle time by overriding Automatic reset-to-minimum functions. It is intended for applications where:

- Multiple Measurements where magnitude is expected within a range of two or three decades, and test voltage must vary with actual resistance measurements.
- When **AUTOMATIC** electrification period and Test Voltage control must be maintained to current industry (and Automatic Mode) settings

This mode prevents the PRS-812 from resetting the Test Voltage and Resistance Range to Minimum at the beginning of each Measurement Test Cycle. In this mode, measurements start at the resistance range selected by the operator, and its commensurate Test Voltage, or the value of the last measurement. Otherwise, it is used similar to the **AUTOMATIC** Mode.

The following summarizes **AUTOMATIC/MANUAL** Mode Operations and assumes that test leads are properly connected.

1. Slide Battery Buss Cut Off switch to **ON** position
2. Press Red **ON/OFF** button once to power up the instrument.
3. Select **AUTOMATIC/MANUAL MODE** by pressing the **MODE** select button until **AUTO** and **MANUAL** appear in the LCD display.
  - a. Pressing the **MODE** button four (4) times selects **AUTOMATIC/MANUAL** Exponential display (1.0EXX).
  - b. Pressing the **MODE** button five (5) times selects **AUTOMATIC/MANUAL** display in Ohms.
4. Set RESISTANCE RANGE SELECTION using the UP (↑) and DOWN (↓) arrow keys.

- a. Range selection is made in one-decade increments and indicated with illuminated LED's.
  - b. For resistance ranges below  $<E03$ , use the LCD displayed decimal point (.) for setting the desired decade. The  $<3$  LED will be illuminated.
5. Press the Green **TEST** button to begin the **AUTOMATIC/MANUAL** Measurement Cycle.
  - a. The instrument will automatically start the Test Cycle from the selected resistance range decade.
  - b. Initial Test Voltage for the selected resistance decade will be applied. For example if the  $10^6$  ohms decade was selected, initial Test Voltage will be 100 Volts.
  - c. At this point the PRS-812's **AUTOMATIC** Mode takes control of the Measurement Test Cycle:
    - (1) Automatically re-adjusts **RESISTANCE RANGE** in accordance with material resistive characteristics
    - (2) Automatically re-adjusts **TEST VOLTAGE** in accordance with material resistive characteristics and industry standards
    - (3) Automatically re-adjusts **ELECTRIFICATION PERIOD** in accordance with material resistive characteristics and industry standards
    - (4) At completion of Test Cycle, displays and **HOLDS** final resistance measurement, test voltage, order of magnitude (LED), analog scale & multiplier, and electrification time at end of electrification period.
- L. The Memory Register: Data Logging and Calculation

As previously described, the PRS-812 Resistance System will acquire and store up to 80 measurements, or data points, in its Memory Register when Record (REC) is activated. Data is entered in memory each time the RESET button is pressed following a measurement. The data in memory can be reviewed for its minimum, maximum and average values by pressing the RECALL button.

1. To Activate the Record Mode press the gray **RECORD/RECALL** button once. **REC** will be displayed in the lower left corner of the instrument's LCD display.
2. To Review Data in the Memory Register press the **RECORD/RECALL** button four times, as follows:
  - a. 1st Press RECORD/RECALL: Provides access to data points in the Memory Register
    - (1) Use UP (↑) and DOWN (↓) arrow keys to scroll through data.
    - (2) You may select a data point and eliminate it by pressing **CLEAR**. All other stored data will shift one slot in the register to replace deleted data.
    - (3) Min, Max and Average of remaining data in Memory will be recalculated.
    - (4) Press **RECORD/RECALL** to proceed, or **RESET** to exit Memory Register and return to normal operations.

**OPERATIONAL NOTE**

You may return the instrument to normal operations from the **RECORD/RECALL** mode at any time by pressing **RESET**.

- b. 2nd Press **RECORD/RECALL**: LCD Displays **MIN** and the lowest recorded resistance value saved in the Memory Register
- c. 3rd Press **RECORD/RECALL**: Displays **MAX** and the highest recorded resistance value saved in the Memory Register

**NOTE**

When displayed, **OL** (Over Level) indicates a measurement greater than ( $>$ )  $2.0 \times 10^{14}$  ohms, beyond the measurement capability of the PRS-812

- d. 4th Press **RECORD/RECALL**: Displays **AVG** and the average of all recorded resistance values saved in the Memory Register

**NOTE**

**OL** (Over Level) measurements greater than ( $>$ )  $2.0 \times 10^{14}$  ohms are not included in displayed average (**AVG**) calculation. **AVG** is the calculated average of all resistance values less than ( $<$ )  $2.0 \times 10^{14}$  ohms, rounded to the first decimal point.

- e. 5th Press **RECORD/RECALL**: Returns PRS-812 System to normal operations

**NOTE**

If **RECALL** is not pressed, a fifth time **OOPS** will be displayed in the LCD when **TEST** is next pressed. To Clear **OOPS**, press **RESET**. The instrument will return to normal operations.

## VII. Instrument Maintenance

### A. Calibration & Repair

1. Instrument Calibration should be performed annually
2. Only Prostat Corporation or their authorized instrument laboratory should perform PRS-812 calibration or repair.
3. Before shipping your instrument to Prostat Corporation for service, contact Prostat calibration & customer service for a Return Material Authorization (RMA) tracking number by the following means: See WARRANTY INFORMATION, below, for further instructions.



## B. General Handling & Maintenance

### 1. Cleaning

- a. Wipe case and LCD with clean, low linting damp cloth
- b. Do not use solvents for cleaning case or LCD

### 2. Handling

- a. Store the instrument in a clean, dry environment. Do not expose the instrument to wet, extremely hot or cold conditions.
- b. Do not drop or cause mechanical shock to your instrument
- c. If the unit is stored in a cold environment, allow it to stabilize at room temperature before powering up the unit.
- d. Remove batteries before storing the instrument for long periods.
- e. Be sure fresh alkaline batteries are installed when beginning an extensive measurement sequence. Periodically check the condition of your batteries by pressing **BATT. TEST**. If **Lo** is indicated, replace your batteries.

## VIII. Warranty Information

### A. Prostat Corporation Warranty

Prostat Corporation expressly warrants that for a period of one (1) year from the date of purchase, that Prostat instruments will be free from defects in material (parts) and workmanship (labor). If Prostat receives notice of such defect during the warranty period, Prostat will replace at its expense such parts that it determines to be defective. Any defective part must be returned to Prostat postage prepaid with proof of purchase date.

Warranty Exclusions – THE FOREGOING EXPRESS WARRANTY IS MADE IN LIEU OF ALL OTHER PRODUCT WARRANTIES, EXPRESS AND IMPLIED, INCLUDING MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, WHICH ARE SPECIFICALLY DISCLAIMED. The express warranty will not apply to defects or damage due to accidents, neglect, misuse, alterations, operator error, or failure to properly maintain, clean, or repair products. Limit of Liability – in no event will Prostat or any seller be responsible or liable for special, incidental, or consequential losses or damages, under any legal theory including but not limited to contract, negligence, or strict liability.

Fulfillment by Prostat of its express warranty obligations described above will be purchaser's exclusive remedy and will be Prostat's and seller's limit of liability for any breach of warranty or otherwise.

### B. Shipping of Warranty Returns

1. Obtain a Return Materials Authorization (RMA) number and shipping address from Prostat customer service. Pack the instrument carefully and ship it prepaid and insured to the proper destination provided by Prostat's customer service department.
2. For detailed shipping instructions and Return Materials Authorization (RMA), contact:



Prostat Corporation  
1072 Tower Lane  
Bensenville, IL 60106  
Telephone: (630) 238-8883 or (855) 782-8421  
Website: [prostatcorp.com/rma](http://prostatcorp.com/rma)

C. Shipping Non-Warranty Items

1. Any Prostat product returned for non-warranty repair or calibration requires a Return Materials Authorization (RMA) number and should be packaged and shipped as described above, and as directed by Prostat's customer service department.
2. The following information must be included with the returned product:
  - a. Description of the problem
  - b. Customer's Purchase Order Number & Prostat's Materials Authorization (RMA) number
  - c. Name, telephone number and fax number of individual contact who can provide more information regarding the problem and related application(s).
  - d. Complete return address.

## PRS-812 Resistance System Specifications

Range:	Resistance from <0.1 (1.0E-1) Ohms to 200 Tera ohms (1.0E+12 ohms). Maximum resistance indication: 200 Tera ohms (2.0E+14 ohms)	
Test Voltages:	<b>Automatic mode Default:</b>	<0.01 to 10 volts Variable 1.0E-1 to 1.0E+4 Ohms Constant Voltage 10 volts $\pm$ <0.2 volts 1.0E+4 to 1.0E+6 Ohms At 10 & 100 Volts 100 volts $\pm$ <2.0 volts 1.0E+6 to 2.0E+14 Ohms
	<b>Manual Mode:</b>	<0.01 to 10 volts Variable 1.0E-1 to 1.0E+4 Ohms 10 volts $\pm$ <0.2 volts 1.0E+3 to 1.0E+9 Ohms 100 volts $\pm$ <2.0 volts 2.0E+5 to 2.0E+14 Ohms
Normal Accuracy:	Overall: $\pm$ <5% at ambient conditions (at 23°C and 30% Rh). Approximate Range Tolerances: 1.0E-1 to 1.0E+1 ohms: $\pm$ 5% Corrected for Test Lead Resistance 1.0E+1 to 1.0E+12 ohms: $\pm$ 2.0% with 10-foot Test Leads 1.0E+12 to 2.0E+14 ohms: $\pm$ 40%	
Display:	Multi-function 2-5/8" x 1-5/8" Liquid Crystal Display with 0.5" digit height. Displays 3-1/2 digits in Ohms, or 1.0EXX in exponential format. Ohms Display indicators: $\Omega$ , K $\Omega$ , M $\Omega$ , G $\Omega$ and T $\Omega$ . Includes 19-segment analog scale (1-10 with 0.5 indication) with x1, x10, & x100 multipliers. Number of Data Points in Memory (0 – 80). Automatic Electrification Time (seconds), or Time required to Manually obtain steady state measurement. Displays data HOLD, BATTERY status, MIN, MAX, AVG, REC and Test Voltage (<10, 10, or 100 V)	
LED Indicators:	14 Color LED's from <10 <sup>3</sup> to >10 <sup>14</sup> ohms. Colors are (RED, GREEN, YELLOW/ORANGE, or Blank/OFF).	
Timer Memory:	Times measurements In Seconds up to 99 seconds (Displayed on LCD) Register stores up to 80 data points (MEM # Displayed after RESET)	
Response & Electrification:	Response from >0.1 to <1.0E06 Ohms: <2.0 seconds Average Measurement Period from 0.1 ohms to 1.0E12 Ohms 2.5 Seconds. Calculated Electrification Period per ANSI/ESD STM11.11, 7.5 second 0.1 ohms to 10E+12 Ohms. Programmed Electrification >1.0E+12 Ohms: 15.0+ seconds	
Power:	Two 9-VDC alkaline batteries. Nominal battery life 25 hours in <b>AUTOMATIC</b> mode, approximately 40 hours in <b>AUTOMATIC/MANUAL</b> mode.	
Dimensions:	4.0" wide x 6.0" long x 2.0" deep.	
Weight:	22 ounces, with batteries	
Open Circuit Current (I):	<4mA @ 100 Volts	
Usage:	Designed for Intermittent use. Not intended for continuous use or production applications.	

## PRS-812 Instrument Controls

FUNCTION/ MODE Toggles Through Six (6) Operation Modes:

MODE	DISPLAYED UNITS	INDICATION	RESIST. RANGE	TEST VOLTS	TEST FUNCTIONS
AUTOMATIC 1 [Default]	1.0EXX IND $\Omega$ - T $\Omega$	AUTO	AUTO.	AUTO.	AUTOMATIC RESISTANCE RANGE, TEST VOLTS, ELECTRIFICATION, DISPLAY HOLD  <b>SEE TABLE NOTE #1</b>
AUTOMATIC 2	OHMS $\Omega$ - T $\Omega$	AUTO	AUTO.	AUTO.	
MANUAL 1	1.0EXX IND $\Omega$ - T $\Omega$	MANUAL	MAN	MAN. or AUTO	TEST ONLY; NO DISPLAY HOLD UL= UNDER DECADE LEVEL OL= OVER DECADE LEVEL  <b>SEE TABLE NOTE #2</b>
MANUAL 2	OHMS $\Omega$ - T $\Omega$	MANUAL	MAN	MAN. or AUTO	
MANUAL/ AUTOMATIC 1	1.0EXX IND $\Omega$ - T $\Omega$	AUTO & MANUAL	MAN. Start AUTO Run	AUTO.	MANUAL SETUP STARTING DECADE, AUTO ADJUST RANGE, TEST VOLTS, ELECTRIFICATION DISPLAY HOLD  <b>SEE TABLE NOTE #3</b>
MANUAL/ AUTOMATIC 2	OHMS $\Omega$ - T $\Omega$	AUTO & MANUAL	MAN. Start AUTO Run	AUTO.	

### TABLE NOTES:

**#1 AUTOMATIC:** RESISTANCE RANGES IN AUTO 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+04 $\Omega$  (0.1 $\Omega$  - < 10K $\Omega$ )  
 @ 10V: 1.0E+04 TO <1.0E+06 $\Omega$  (10K $\Omega$  - < 1M $\Omega$ )  
 @100V: 1.0E+06 TO <2.0E+12 $\Omega$  (1M $\Omega$  - <200T $\Omega$ ) **See Note Below**

**#2 MANUAL:** RESISTANCE RANGES IN MAN 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+05 $\Omega$  (0.1 $\Omega$  - <100K $\Omega$ )  
 @ 10V: 1.0E+03 TO <1.0E+09 $\Omega$  (1K $\Omega$ - <1G $\Omega$ )  
 @100V: 2.0E+05 TO <2.0E+12 $\Omega$  (200K $\Omega$ -< 200T $\Omega$ ) **See Note Below**

**#3 AUTO-MANUAL:** (Same as AUTOMATIC)  
 RESISTANCE RANGES IN AUTO-MANUAL 0.1 $\Omega$  TO <2.0E+12 $\Omega$  as follows  
 @<10V: 0.1 TO <1.0E+04 $\Omega$  (0.1 $\Omega$  - < 10K $\Omega$ )  
 @ 10V: 1.0E+04 TO <1.0E+06 $\Omega$  (10K $\Omega$  - < 1M $\Omega$ )  
 @100V: 1.0E+06 TO <2.0E+12 $\Omega$  (1M $\Omega$  - <200T $\Omega$ ) **See Note Below**

**NOTE: It is capable of measuring up to 2.0x10<sup>14</sup> ohms with tolerance depending on procedures and conditions.**

Resistance Range Select. 2 Triangular button Arrows: UP ( $\uparrow$ ) and DOWN ( $\downarrow$ ). Select Resistance Range in single decades in Manual and Automatic/Manual modes

Test Volts Manual Selection of <10, 10 or 100 volts in Manual Mode

Record/ Recall Turns Memory Register ON if OFF. Provides access to all data in Memory Regis-

	ter. Calculates and Displays Minimum, Maximum and Average of data stored in Memory Register.
Clear	Erases data in Memory Register; if in HOLD mode, discards most recent Held Value
ON/OFF	Power-up, perform functional & Battery tests, Power-down if ON.
Batt. Test	Displays GOOD on LCD if acceptable voltage or Lo if unacceptable
Reset	Enters (saves) data into Memory Register, Clears HOLD and Display.
Test	Begins measurement sequence.
Battery Buss Cut Off	ON/OFF Switch isolates batteries from instrument circuits for storage & transport

## NOTES

## NOTES



Specifications are subject to change without notice.  
All Prostat trademarks and trade names are the property of Prostat Corporation.  
All other trademarks and trade names are the property of their respective companies.



CARRIED BY  
PROFESSIONALS

P R O F E S S I O N A L   S T A T I C   C O N T R O L   P R O D U C T S

Prostat Corporation

Corporate Headquarters • 1072 Tower Lane • Bensenville, IL 60106 • 630-238-8883 • Fax: 630-238-9717 • 1-855-STATIC1 • [www.prostatcorp.com](http://www.prostatcorp.com)